AMENDMENTS TO THE SPECIFICATION

Previously presented:

[0031] As shown in Figure 2A, the outer facing layers and the plies that form the middle layer of the corner post wall are the same thickness.